

## Hygienic cleaner for the pollen filter box mit 996 Hygienic Cleaner for Pollen Filter Box

### Important warnings

- Use airco well® 996 hygienic cleaner for pollen filter boxes every time the pollen filter is replaced.
- Observe the manufacturer's instructions when installing and removing the components.
- No rinsing is required after cleaning with airco well® 996 Pollen Filter Box Hygienic Cleaner, not even with water.
- Before starting work, switch off the ignition, fans and air-conditioning unit.
- Carefully protect any electronic components in the cleaning area from moisture. Do not spray the cleaner directly onto the fan motor.
- If there are already any unpleasant odours or if any allergy symptoms have arisen, we recommend cleaning the evaporator in advance with airco well® 994 A/C System Hygienic Cleaner. We recommend cleaning the air-conditioning unit annually, even if there are no odours.



### Attention!

- The following points must be observed when cleaning high-voltage vehicles (BEV and hybrid):
- Work on high-voltage vehicles may be carried out only by trained and authorised staff holding specialist certification (observe national regulations).
- Before starting work, high-voltage vehicles must be de-energised by staff authorised to do so and in accordance with the manufacturer's instructions.
- There is a risk of serious injury and damage to the vehicle in the event of non-compliance with these points.

### Application

1. Remove the pollen filter.
2. Spray a TUNAP microfibre cloth with airco well® 996 hygienic cleaner for pollen filter boxes.
3. Wipe out the pollen filter box and the surrounding air ducts with the damp TUNAP microfibre cloth.
4. Then remove the surface spray nozzle from the can, mount the mist probe and carefully spray into the hard-to-reach areas.
5. Allow the cleaner to flash off for approx. 10 minutes.
6. Insert the new pollen filter.

# Service Information



The information provided in this service information is the result of careful investigations. Insofar as it relates to the application, it should be regarded as a recommendation based on experience. However, due to the diversity of application and working methods, we cannot accept any liability. Therefore, a contractual legal relationship is not established and no secondary obligations arise from any purchase contracts.

The service information is only valid in its current version.

TUNAP (U.K) Limited | Unit L4 Deacon Trading Estate, Morley Road, Tonbridge, Kent TN9 1RA | Telephone +44 (0) 1732 365163 | e-Mail: sales@tunap.co.uk

**TUNAP.com**